



## COMPONENT REPAIR CAPABILITIES

Contact us:

[info@apacs.aero](mailto:info@apacs.aero)

+603 5870 0500

Mar-24

© 2023 Asia Pacific Aircraft Component Services Sdn Bhd. All rights reserved



**Asia Pacific Aircraft Component Services Sdn Bhd**  
**Component Repair Capabilities**  
**Version: March 2024**

Contact us:  
[info@apacs.aero](mailto:info@apacs.aero)  
+603 5870 0500

MPN	Description	CMMA/TA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE	ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
04P23-10	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-31-42;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000		YES	YES	YES	YES	YES	YES	NO
04P23-12	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-31-42;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000		YES	YES	YES	YES	YES	YES	NO
04P23-8	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-31-42;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000		YES	YES	YES	YES	YES	YES	NO
07P95-1	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;		YES	YES	YES	YES	YES	YES	NO
07P95-2	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;		YES	YES	YES	YES	YES	YES	NO
07P95-3	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;		YES	YES	YES	YES	YES	YES	NO
07P95-4	VALVE PNEUMATIC RELAY	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;		YES	YES	YES	YES	YES	YES	NO
07P95-7	VALVE PNEUMATIC RELAY	75-31-43;	GRIMES AEROSPACE CO	YES	YES	YES	B747;B767;A330;A300;A310;MD11;		YES	YES	YES	YES	YES	YES	NO
07P95-8	VALVE PNEUMATIC RELAY	75-31-43;	GRIMES AEROSPACE CO	YES	YES	YES	B747;B767;A330;A300;A310;MD11;		YES	YES	YES	YES	YES	YES	NO
07P95-9	PNEUMATIC RELAY VALVE	75-31-43;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;A310;A330		YES	YES	YES	NO	YES	YES	NO
1001000-3	VALVE-STARTER-AIR	80-11-18;	HAMILTON SUNSTRAND	YES	YES	YES	A330;PW4000;		YES	YES	YES	YES	YES	YES	NO
1001000-4	VALVE-STARTER-AIR	80-11-18;	HAMILTON SUNSTRAND	YES	YES	YES	A330;PW4000;		YES	YES	YES	YES	YES	YES	NO
10-1327-1	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;B757;B767;		YES	YES	YES	YES	YES	YES	NO
10-1327-2	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;B757;		YES	YES	YES	YES	YES	YES	NO
10-1327-3	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;B757;		YES	YES	YES	YES	YES	YES	NO
10-1327-4	FLUORESCENT WINDOW LIGHT	33-20-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B757;		YES	YES	YES	YES	YES	YES	NO
10-1733-1	FLUORESCENT WINDOW LIGHT	33-21-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;B757;		YES	YES	YES	YES	YES	YES	NO
10-1733-2	FLUORESCENT WINDOW LIGHT	33-21-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;B757;		YES	YES	YES	YES	YES	YES	NO
10-1733-3	FLUORESCENT WINDOW LIGHT	33-21-39;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;B757;		YES	YES	YES	YES	YES	YES	NO
102-00090	SENSOR-OIL TEMPERATURE	79-32-15;	NORWICH AERO PRODUCTS INC	YES	NO	NO	A320_Fam;CFM56;		YES	YES	YES	YES	YES	YES	NO
10-609660-9	IGNITION LEADS	74-21-08;	UNISON INDUSTRIES, LLC	YES	YES	YES	PW4000;		YES	YES	YES	YES	YES	YES	NO
106-1-1100-02	ACTUATOR-APU	49-16-51;	ELEKTRO-METALL EXPORT GMBH	YES	YES	YES	A320_Fam;A330;A340;		YES	YES	YES	YES	YES	YES	NO
106-1-1100-03	APU ACTUATOR	49-16-51;	ELEKTRO-METALL EXPORT GMBH	YES	YES	YES	A320; A330; A340		YES	YES	YES	NO	NO	NO	NO
10-62090-42	AUDIO CONTROL PANEL	23-50-38;	AVTECH TYEE, INC	YES	YES	YES	B737NG;B757;		YES	YES	YES	YES	YES	YES	NO
10-62090-64	AUDIO CONTROL PANEL	23-50-23;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;		YES	YES	YES	NO	YES	YES	NO
10-62090-77	AUDIO CONTROL PANEL	23-50-74;	AVTECH TYEE, INC	YES	YES	YES	B737NG;A330;		YES	YES	YES	NO	YES	YES	NO
1108V0100-1	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A300;A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1108V0100-2	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A300;A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1108V0100-3	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	PW4000;		YES	YES	YES	YES	YES	YES	NO
1109V0300	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A330;A300;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1109V0300-1	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;A330;A300;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1109V0300-2	DUAL-THREE-WAY PNEUM. SOLENOID VALVE	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	PW4000;		YES	YES	YES	YES	YES	YES	NO
1109V0300-4	SOLENOID-HPV SEQUENCE FLOW CONTROL	75-33-10;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	767-A300;A330;MD-11		YES	YES	YES	NO	NO	YES	NO
1110V0500-2	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A310;MD11;PW4000;		YES	YES	YES	YES	NO	YES	NO
1110V0500-3	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A310;MD11;PW4000;		YES	YES	YES	YES	NO	YES	NO
1110V0500-4	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A310;MD11;PW4000;		YES	YES	YES	YES	NO	YES	NO
1110V0500-5	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A310;MD11;PW4000;		YES	YES	YES	NO	YES	YES	NO
1110V0500-6	TURBINE BLADE/VANE COOLING VALVE	75-24-12;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B767;MD11;PW4000;		YES	YES	YES	YES	NO	YES	NO
1110V0700-3	TURBINE BLADE/VANE COOLING VALVE (TBVC)	75-25-11;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;PW4000;		YES	YES	YES	YES	YES	YES	NO
1110V0700-4	TURBINE BLADE/VANE COOLING VALVE (TBVC)	75-25-11;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	PW4000;		YES	YES	YES	YES	YES	YES	NO
1110V0700-5	TURBINE BLADE/VANE COOLING VALVE (TBVC)	75-25-11;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0300-1	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0300-4	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0300-5	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0300-6	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A300;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700-10	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700-4	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700-5	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700-6	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700-7	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700-8	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
1115V0700-9	BLEED AIR VALVE 9TH-STG.	75-31-40;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
11698-000	HEAT EXCHANGER-AIR/OIL DGDS	24-11-01;	AMETEK AEROSPACE	YES	YES	YES	B747;B767;A330;A300;A310;MD11;PW4000;		YES	YES	YES	YES	YES	YES	NO
11-841193-2	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
11-841193-3	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
11-841193-4	OIL / FUEL HEAT EXCHANGER	79-21-25;	SECAN / HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
1211313-010	ACTUATOR-VARIABLE STATOR	75-32-13;	ARKWIN INDUSTRIES INC.	YES	YES	YES	B737CL;B737NG;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-10	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-11	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	NO	YES	YES	NO
121664-12	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-3	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-4	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-5	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-6	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-7	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-8	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121664-9	ACTUATOR-BALLSCREW	75-31-61;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-13	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-14	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-16	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-17	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-18	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-19	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-21	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-3	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-4	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-6	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;		YES	YES	YES	YES	YES	YES	NO
121666-7	ACTUATOR-BALLSCREW MASTER	75-31-51;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;A320_Fam;CFM56;		YES	YES	YES	YES	YES	YES	NO











**Asia Pacific Aircraft Component Services Sdn Bhd**  
**Component Repair Capabilities**  
**Version: March 2024**

Contact us:  
[info@apacs.aero](mailto:info@apacs.aero)  
+603 5870 0500

MPN	Description	CMMA/T	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
4205401	PUMP-HYDRAULIC	29-11-33;	PARKER HANNIFIN MANUFACTURING	YES	YES	YES	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
420262	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A320;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
420294	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A320;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
420295	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A320;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	YES
4313100-01-6600	CONVECTION OVEN DF3000 LH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
4313101-01-6600	CONVECTION OVEN DF3000 RH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
4323070-01-6626	STEAM OVEN DS3075 LH (EXTENDED VERSION)	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	B777	YES	YES	YES	YES	YES	YES	NO
4323100-01-6622	STEAM OVEN DS3000 LH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
4323101-01-6622	STEAM OVEN DS3000 RH	25-35-12;	B/E AEROSPACE INC.	YES	YES	YES	B777	YES	YES	YES	YES	YES	YES	NO
45-0351-1	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
45-0351-2	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
45-0351-3	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
45-0351-4	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
45-0351-5	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
45-0351-6	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
45332-8036	OIL / FUEL HEAT EXCHANGER	79-21-26;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
45332-8039	OIL / FUEL HEAT EXCHANGER	79-21-26;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	YES
45731-1381	HEATER-SERVO FUEL	73-11-24;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B737NG;A320_Fam;A340;CFM56-7B;CFM56-5C;CFM56-5B	YES	YES	YES	YES	YES	YES	NO
45731-1382	HEATER-SERVO FUEL	73-11-77;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	YES
45731-1385	HEATER-SERVO FUEL	73-21-84;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	YES
45731-1386	HEATER-SERVO FUEL	73-21-84;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	YES
45731-1391	COOLER-IDG OIL	73-11-64;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
45731-1392	COOLER-IDG OIL	73-11-65;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	CFM56;	YES	YES	YES	YES	YES	YES	NO
45731-1393	COOLER-IDG OIL	73-11-65;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	YES
45D31	SWITCH-DIFFERENTIAL PRESSURE	73-34-03;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	A320_Fam;CFM56-5A;CFM56-5B;	YES	YES	YES	YES	YES	YES	NO
45D31-2	SWITCH-DP (PPK)	73-34-04;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	A330;A340;CFM56-5C;	YES	YES	YES	YES	YES	YES	NO
45D32	SWITCH-LOW OIL PRESSURE	79-33-02;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
47111-1201	EXCHANGER, HEAT - IDG OIL/FUEL	79-21-15;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
47111-1203	EXCHANGER, HEAT - IDG OIL/FUEL	79-21-15;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	YES
47111-1204	EXCHANGER, HEAT - IDG OIL/FUEL	79-21-15;	MEGGITT AEROSPACE LIMITED	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
50U683	IGNITION LEADS	74-21-08;	UNISON INDUSTRIES, LLC	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
5145-1-42	AUDIO CONTROL PANEL	23-50-38;	AVTECH TYEE, INC	YES	YES	YES	B737NG;B747;	YES	YES	YES	YES	YES	YES	NO
5145-1-60	AUDIO CONTROL PANEL	23-50-15;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
5145-1-61	AUDIO CONTROL PANEL	23-50-15;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
5145-1-62	AUDIO CONTROL PANEL	23-50-15;	AVTECH TYEE, INC	YES	YES	YES	B737CL;	YES	YES	YES	YES	YES	YES	NO
5145-1-64	AUDIO CONTROL PANEL	23-51-23;	AVTECH TYEE, INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	YES
5145-1-77	AUDIO CONTROL PANEL	23-50-74;	AVTECH TYEE, INC	YES	YES	YES	B737NG;A330;	YES	YES	YES	YES	YES	YES	NO
5145-1-83	SEALED AUDIO CONTROL PANEL	23-44-00;	AVTECH TYEE, INC	YES	YES	YES	B737NG;B747;	YES	YES	YES	YES	YES	YES	NO
5145-1-88	SEALED AUDIO CONTROL PANEL	23-44-02;	AVTECHTYEE	YES	YES	YES	B737 Family	YES	YES	YES	YES	YES	YES	NO
51H336	VALVE OIL COOLER BYPASS	79-21-16;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
51R148	HEATER-SERVO FUEL	73-21-84;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
51U711	SWITCH DIFFERENTIAL PRESSURE	73-11-10;	CUSTOM CONTROL SENSORS INC	YES	YES	YES	B747;B767;A320;A300;A310;MD11;	YES	YES	YES	YES	YES	YES	NO
514674-4	ACTUATOR - RAM AIR INLET	21-20-36;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;	YES	YES	YES	YES	YES	YES	NO
5507-910-0	CHIP DETECTOR	79-21-57;	ZODIAC SERVICES EUROPE (ZSE)	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-002	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	NO	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-005	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-006	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-007	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-02R	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
568-1-27202-05R	PUMP-FUEL	28-21-51;	EATON LIMITED	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
582-3	COMPRESSOR	25-31-12		YES	YES	YES		NO	NO	NO	NO	NO	NO	NO
5830201-106	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-107	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B747;B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-108	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-109	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-110	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830201-111	ACTUATOR TURBINE COOLING AIR VALVE	75-24-14;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-105	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-106	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-108	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-109	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-15;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830202-111	VALVE-TURBINE CASE CLG	75-24-15;	PARKER HANNIFIN MANUFACTURING	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
5830203-104	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-09;	PARKER HANNIFIN CORPORATION	YES	YES	YES	B767;A300;A310;MD11;PW4000;	YES	YES	YES	YES	YES	YES	NO
5830203-105	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-09;	PARKER HANNIFIN CORPORATION	YES	YES	YES	PW4000;	YES	YES	YES	YES	YES	YES	NO
585-14	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-16	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-17	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-23	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-30	COMPRESSOR	25-31-16	B/E AEROSPACE	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
585-6	COMPRESSOR	25-31-15	B/E AEROSPACE	YES	YES	YES		NO	NO	NO	NO	NO	NO	NO
585-8	COMPRESSOR	25-31-15	B/E AEROSPACE	YES	YES	YES		NO	NO	NO	NO	NO	NO	NO
585-9	COMPRESSOR	25-31-15	B/E AEROSPACE	YES	YES	YES		YES	NO	NO	NO	NO	NO	NO
5930638-102	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-30;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930638-103	LOW PRESSURE TURBINE CASE COOLING VALVE	75-24-30;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930639-102	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-31;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930639-103	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-31;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
5930639-104	HIGH PRESSURE TURBINE CASE COOLING VALVE	75-24-31;	PARKER HANNIFIN CORPORATION	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
62197-001-001	WATER BOILER	25-35-95;	Safran Cabin Germany	YES	YES	YES	B737CL;B737NG;B767;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	YES
623977	PUMP-HYDRAULIC	29-11-34;	EATON AEROSPACE	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
642D0010-503	VALVE-ANTI-ICE	30-21-52;	MEGGITT CONTROL SYSTEMS	YES	YES	YES	A320_Fam;A340;CFM56;	YES	YES	YES				





**Asia Pacific Aircraft Component Services Sdn Bhd**  
**Component Repair Capabilities**  
**Version: March 2024**

Contact us:  
[info@apacs.aero](mailto:info@apacs.aero)  
+603 5870 0500

MPN	Description	CHM/TA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DOCA	CAAC	JCAB
9387M24P09	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P14	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P16	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P17	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
9387M24P18	IGNITION LEADS	74-21-15;	UNISON INDUSTRIES, LLC	YES	YES	YES	A320_Fam;CFM56;	YES	YES	YES	YES	YES	YES	NO
971844	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
972630	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
974540	HYDRAULIC MOTORPUMP ASSEMBLY	29-10-72;	EATON LIMITED	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
974800	PUMP-HYDRAULIC	29-10-55;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
974947	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
974976	PUMP-HYDRAULIC	29-10-41;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56;PW4000;	YES	YES	YES	YES	YES	YES	NO
975A0000-02	ACTUATOR-RAM AIR INLET	21-53-51;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	NO	NO
975A0000-03	ACTUATOR-RAM AIR INLET	21-53-51;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	NO	NO
976A0000-02	ACTUATOR-RAM AIR OUTLET	21-53-52;	LIEBHERR-AEROSPACE-TOULOUSE SAS	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	NO	NO
9910-00000-01	BOWL	38-32-42		YES	YES	NO		YES	NO	NO	NO	NO	NO	NO
A05000	ACTUATOR ASSY	24-09-01;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
A05800	ACTUATOR ASSY	24-09-01;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
A06000	ACTUATOR ASSY	24-09-02;	SITEC AEROSPACE GMBH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
A08000	ACTUATOR ASSY	24-09-03;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
ACP2788A02	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
ACP2788A04	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
ACP2788A05	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
ACP2788A01	ACP-AUDIO CONTROL PANEL	23-51-22;	COBHAM Avionics	YES	YES	YES		YES	YES	YES	YES	YES	YES	NO
ACP2788AD01	ACP-AUDIO CONTROL PANEL	23-51-54;	COBHAM Avionics	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
ACP2788AE01	ACP-AUDIO CONTROL PANEL	23-51-55;	COBHAM Avionics	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
ACP2788AF01	ACP-AUDIO CONTROL PANEL	23-51-01;	COBHAM Avionics	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
C143620-2	VALVE 8TH STAGE CHECK VALVE	36-11-52;	MICROTECHNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C143620-2M2	VALVE 8TH STAGE CHECK VALVE	36-11-52;	MICROTECHNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C143620-3	VALVE 8TH STAGE CHECK VALVE	36-11-52;	MICROTECHNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C148275-1	VALVE NACELE COOLING	75-26-11;	MICROTECHNICA S.r.l.	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
C20105000	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C20105000-1	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C20105000-2	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C20105100	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C20105100-1	TACHOMETER	32-46-15;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C20288000-1	ACCUMULATOR-BRAKE	32-46-06;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C20288000-2	ACCUMULATOR-BRAKE	32-46-06;	Safran Landing Systems	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
C24960000-1	VALVE-SAFETY	29-11-67;	Safran Landing Systems	YES	YES	YES	A320_Fam;A330;A340;A300;A310;	YES	YES	YES	YES	YES	YES	NO
C24966000	VALVE SAFETY	29-11-67;	Safran Landing Systems	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
C8210010	VALVE-DRAIN	29-11-13;	GOODRICH ACTUATION SYSTEMS SAS	YES	YES	YES	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D05000	VALVE-FILL AND DRAIN	38-10-02;	SITEC AEROSPACE GMBH	YES	YES	YES	A320_Fam;A330;	YES	YES	YES	YES	YES	YES	NO
D05A00	VALVE-FILL/DRAIN	38-10-02;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
D05C00	VALVE-FILL AND DRAIN	38-10-02;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
D23119500	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119500-1	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119510	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
D23119510-1	ELECTRICAL BOX	32-57-09;	Safran Landing Systems	YES	YES	NO	A320_Fam;A340;	YES	YES	YES	YES	YES	YES	NO
D23119550	BOX-ELECTRICAL,NLGI	32-57-11;	Safran Landing Systems	YES	YES	NO	A330;A340;	YES	YES	YES	YES	YES	YES	NO
D23119750	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119750-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119751	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119751-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119760	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119760-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119761	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119770-1	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
D23119771	ELECTRICAL BOX	32-57-17;	Safran Landing Systems	YES	YES	NO	A320_Fam;	YES	YES	YES	YES	YES	YES	NO
E61751-00-0001	HALON PRESSURE REDUCER	26-20-10;	B/E SYSTEMS GMBH	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
E61751-00-0002	HALON PRESSURE REDUCER	26-20-10;	B/E SYSTEMS GMBH	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
E61751-00-0003	HALON PRESSURE REDUCER	26-20-10;	B/E SYSTEMS GMBH	YES	YES	NO	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
FA00631B	FILTER-FUEL NOZZLE	73-11-45;	Safran Filtration systems	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
FA00631C	FILTER-FUEL NOZZLE	73-11-45;	Safran Filtration systems	YES	YES	YES	B737NG;CFM56;	YES	YES	YES	YES	YES	YES	NO
FA00914D	FILTER-FUEL DOWN STREAM	73-11-47;	Safran Filtration systems	YES	YES	YES	B737CL;A320_Fam;A340;CFM56;	YES	YES	YES	YES	YES	YES	NO
FCM9130-01	MODULE - FLUSH CONTROL	38-31-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
FCU9811-01	CONTROL UNIT-FLUSH	38-32-73;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
FCU9816	CONTROL UNIT-FLUSH	38-32-73;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
FRH40003H	DRAIN VALVE-WASTE WATER	38-30-30;	Eaton Aerospace LTD	YES	YES	YES	B737NG;A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
FV9300-00	VALVE ASSY-FLUSH	38-32-79;	Diehl Aviation Gilching GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
FV9300-01	VALVE ASSY-FLUSH	38-32-41;	Diehl Aviation Gilching GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
GS40DAS1-01	VALVE-WASTE DRAIN	38-32-49;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
GS40DQ72	SEPARATOR-WASTE	38-34-19;	Diehl Aviation Gilching GmbH	YES	YES	NO	B767;A330;A340;	YES	YES	YES	YES	YES	YES	NO
G7402-05	PANEL-SINGLE ADF CONTROL	34-50-48;	GABLES ENGINEERING INC.	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	YES
G7403-03	ADF PANEL	34-50-53;	GABLES ENGINEERING INC.	YES	YES	YES	B737NG;BDIV;	YES	YES	YES	YES	YES	YES	YES
G7404-124	RADIO TUNING PANEL	23-10-37;	GABLES ENGINEERING INC.	YES	YES	YES	B737NG;BDIV;EMB190;	YES	YES	YES	YES	YES	YES	YES
G7500-03	PANEL-VHF NAV CONT	34-50-57;	GABLES ENGINEERING INC.	YES	YES	YES	B737CL;B737NG;BDIV;	YES	YES	YES	YES	YES	YES	YES
GTA43-2	VALVE-HEAT EXCHANGER ENG AIR/OIL	79-21-24;	HAMILTON SUNDRAND	YES	YES	YES	A330;PW4000;	YES	YES	YES	YES	YES	YES	NO
JS40A11-300	TOILET ASSY	38-32-41;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
JS40A11-500	TOILET ASSY	38-32-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
JS40A11-510	TOILET ASSY	38-32-44;	Diehl Aviation Gilching GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
JS40A11-520	TOILET ASSY	38-32-42;	Diehl Aviation Gilching GmbH	YES	YES	YES	A320_Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO





**Asia Pacific Aircraft Component Services Sdn Bhd**  
**Component Repair Capabilities**  
**Version: March 2024**

Contact us:  
[info@apacs.aero](mailto:info@apacs.aero)  
+603 5870 0500

MPN	Description	CMMA/TA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DGCA	CAAC	JCAB
J54042-300	TOILET ASSY	38-32-41;	Diehl Aviation Gilling GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
J54042-500	TOILET ASSY	38-32-42;	Diehl Aviation Gilling GmbH	YES	YES	YES	B737NG;A330;A340;	YES	YES	YES	YES	YES	YES	NO
J54042-510	TOILET ASSY	38-32-44;	Diehl Aviation Gilling GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
J54042-515	TOILET ASSY	38-32-44;	Diehl Aviation Gilling GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
J54042-520	TOILET ASSY	38-32-42;	Diehl Aviation Gilling GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
L83A13-604	VALVE-WATER, DRAIN	28-11-22;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
L83A13-609	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
L83A13-610	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
L83A13-611	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
L83A13-614	VALVE-WATER, DRAIN	28-11-22;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
L83A13-615	VALVE-WATER, DRAIN	28-11-22;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
L83A13-616	VALVE-WATER, DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
L83A602	VALVE WATER DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A320 Fam;A330;A340;A310;	YES	YES	YES	YES	YES	YES	NO
L83A603	VALVE WATER DRAIN	28-11-11;	ZODIAC AEROTECHNICS	YES	YES	YES	A310;	YES	YES	YES	YES	YES	YES	NO
N40-1A10100-101	HANDBET COCKPIT	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1A10102-101	HANDBET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GMBH & Co. KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	NO	YES	YES	NO
N40-1A40204-102	HANDBET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	NO	YES	YES	NO
N40-1A40212-102	INTERPHONE HANDBET	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B10100-000	HANDBET, FLIGHT DECK, PAX, BLACK	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B10100-101	HANDBET COCKPIT	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20203-102	HANDBET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A330;	YES	YES	YES	YES	YES	YES	NO
N40-1B20212-102	HANDBET-CABIN	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20215-000	HANDBET, CABIN, PAX, FOGGY (VD9240)	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20215-102	HANDBET WITH SUPPORT BRACKET CABIN, PAX	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B20218-102	HANDBET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	NO	YES	YES	NO
N40-1B30203-102	HANDBET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B30212-000	HANDBET WITH SUPPORT BRACKET	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	NO	YES	YES	NO
N40-1B40203-102	HANDBET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B40204-102	HANDBET-CABIN, FLIGHT ATTENDANT	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B40212-102	HANDBET-CABIN	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
N40-1B40215-102	HANDBET-CABIN	44-10-03;	HOLMBERG GMBH & CO.KG	YES	YES	NO	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
PV3-240-18	ENG DRIVEN HYD PUMP(A SYS)	29-10-61;	EATON AEROSPACE	YES	YES	YES	B737;CFM56-7B	YES	YES	YES	NO	YES	YES	NO
PV3-300-13E	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56-PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13F	PUMP-HYDRAULIC	29-10-41;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56-PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13H	PUMP-HYDRAULIC	29-10-41;	EATON AEROSPACE	YES	YES	YES	A330;A340;CFM56-PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13K	PUMP-HYDRAULIC	29-10-41;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56-PW4000;	YES	YES	YES	NO	YES	YES	NO
PV3-300-13L	PUMP-HYDRAULIC	29-10-55;	EATON LIMITED	YES	YES	YES	A330;A340;CFM56-PW4000;	YES	YES	YES	YES	YES	YES	NO
R295530-1	ROLLER	25-51-18;	TELAIR INTERNATIONAL GMBH	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
S283A305-1	ANTICOLLISION LIGHT UPPER FUSELAGE	33-42-03;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
S283A305-2	ANTICOLLISION LIGHT, LOWER FUSELAGE	33-42-04;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	YES	YES	YES	NO
S283A321-1	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	NO	YES	YES	NO
S283A321-2	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	NO	YES	YES	NO
S283A321-3	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
S283A321-4	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	NO	YES	YES	NO
S283A321-5	RETRACTABLE LANDING LIGHT, LH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737CL;B737NG;EMB190;	YES	YES	YES	YES	YES	YES	NO
S283A321-6	RETRACTABLE LANDING LIGHT, RH	33-42-07;	HONEYWELL INTERNATIONAL INC	YES	YES	YES	B737NG;	YES	YES	YES	NO	YES	YES	NO
S417N514-301	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	NO	YES	YES	NO
S417N514-48	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	YES	YES	YES	NO
S417N514-58	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	NO	YES	YES	NO
S417N514-70	CEILING LIGHT	33-21-14;	DIEHL AEROSPACE GmbH	YES	YES	YES	B737NG;B757;	YES	YES	YES	NO	YES	YES	NO
S8209L1A1-1483	ACCUMULATOR-HYDRAULIC	29-11-12;	HYDAC SYSTEMS & SERVICES	YES	YES	YES	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
S8209L1A1-1484	ACCUMULATOR-HYDRAULIC	29-11-12;	HYDAC SYSTEMS & SERVICES	YES	YES	YES	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
T9A115-00	TOILET ASSY LH	38-31-61;	Diehl Aviation Gilling GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
T9A116-00	TOILET ASSY	38-31-61;	Diehl Aviation Gilling GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
T9A125-00	TOILET ASSY RH	38-31-61;	Diehl Aviation Gilling GmbH	YES	YES	YES	A330;A340;	YES	YES	YES	YES	YES	YES	NO
T9A126-00	TOILET ASSY	38-31-61;	Diehl Aviation Gilling GmbH	YES	YES	YES	A330;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03CE00-02	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03CE01-01	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03CE01-02	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03CE11-02	SEAT, FIRST OFFICER	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE00-01	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE00-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE01-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE02-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE03-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE11-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE13-02	SEAT, CAPTAIN	25-11-31;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI1-03PE00-05	ARMREST, CAPTAIN ASSY	25-11-31;	STELIA AEROSPACE	NO	NO	NO	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE10-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A300;A310;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE11-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A300;A310;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13PE10-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A300;A310;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE00-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE01-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE10-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE11-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE20-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE21-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE30-01	SEAT, FIRST OFFICER	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13CE31-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-13PE00-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320 Fam;A330;A340;	YES	YES	YES	YES	YES	YES	NO



**Asia Pacific Aircraft Component Services Sdn Bhd**  
**Component Repair Capabilities**  
**Version: March 2024**

Contact us:  
[info@apacs.aero](mailto:info@apacs.aero)  
+603 5870 0500

MPN	Description	MMATA	OEM	Test/ Inspection	Repair	Overhaul	USABILITY / AIRCRAFT TYPE / ENGINE TYPE	EASA	FAA	CAAM	CAAS	DOCA	CAAC	JCAB
TAAI2-33PE01-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE10-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE11-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE20-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE21-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE30-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI2-33PE31-01	SEAT, CAPTAIN	25-11-37;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE00-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE01-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE02-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE10-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE11-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE12-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE20-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE21-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE22-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE30-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE31-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03CE32-01	SEAT, FIRST OFFICER	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE00-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE01-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE02-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE10-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE11-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE12-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE20-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE21-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE22-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE31-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-03PE32-01	SEAT, CAPTAIN	25-11-46;	STELIA AEROSPACE	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04M20-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04M30-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04M40-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-04M50-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
TAAI3-24M20-01	THIRD OCCUPANT SEAT (MECHANICAL)	25-11-47;	STELIA AEROSPACE	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
VA4110	FAN-RECIRCULATION	21-21-18;	DieH Aviation Gilching GmbH	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
VD3810	MIXED FLOW FAN	21-21-12;	DieH Aviation Gilching GmbH	YES	YES	YES	A320_Fam/A330/A340/A300/A310;	YES	YES	YES	YES	YES	YES	NO
VD3820	MIXED FLOW FAN	21-21-11;	DieH Aviation Gilching GmbH	YES	YES	YES	A320_Fam/A330/A340/A300/A310;	YES	YES	YES	YES	YES	YES	NO
VD3820-01	MIXED FLOW FAN	21-21-11;	DieH Aviation Gilching GmbH	YES	YES	YES	A320_Fam/A330/A340/A300/A310;	YES	YES	YES	YES	YES	YES	NO
VD3900-03	FAN-RECIRCULATION CABIN	21-21-16;	DieH Aviation Gilching GmbH	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
VD3901-00	FAN-RECIRCULATION CABIN	21-21-16;	DieH Aviation Gilching GmbH	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
VD3909-00	FAN-RECIRCULATION CABIN	21-21-19;	DieH Aviation Gilching GmbH	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
VD3920	FAN-EXTRACTION AFT CARGO	21-21-14;	DieH Aviation Gilching GmbH	YES	YES	YES	A320_Fam/A330/A340;	YES	YES	YES	YES	YES	YES	NO
VR4100-02	FAN RECIRCULATION	21-21-17;	DieH Aviation Gilching GmbH	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
VR4100-03	FAN-RECIRCULATION	21-21-17;	DieH Aviation Gilching GmbH	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
VR4100-04	FAN-RECIRCULATION	21-21-17;	DieH Aviation Gilching GmbH	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
WV9135-01	VALVE-WATER SHUTOFF	38-31-53;	DieH Aviation Gilching GmbH	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO
5145-1-106	SEALED AUDIO CONTROL PANEL	23-50-04	AVTECH TYEE, INC	YES	YES	NO	B737 Family	YES	YES	YES	YES	YES	YES	NO
5145-1-107	SEALED AUDIO CONTROL PANEL	23-50-04	AVTECH TYEE, INC	YES	YES	NO	B737 Family	YES	YES	YES	YES	YES	YES	NO
63292146-1	PRECOOLER CONTROL VALVE (PCCV)	36-00-01	HONEYWELL INTERNATIONAL INC	YES	YES	NO	B737NG	YES	YES	YES	YES	YES	YES	NO
J540A34-100	VACUUM GENERATOR	38-32-55	DieH Aviation Gilching GmbH	YES	YES	YES	A330/A340	YES	YES	YES	YES	YES	YES	NO
YG101-04	GUIDE-Y	25-51-02	HONEYWELL INTERNATIONAL INC	YES	YES	YES	A330/A340;	YES	YES	YES	YES	YES	YES	NO